

# SELECTION GUIDE

BEST PRODUCTS CHOICE FOR DIFFERENT CUTTING AND GRINDING MACHINES



Diameter	Machine		Product Quality Mark									
	Drive type	Power (W)	Cutting				Grinding		Flap discs			
100	Electric	<500	A	20A	16A	A	20A	A	Z			
		500-700	E	CER		E		Z	SA			
	Battery	>300	A	20A	16A	A	20A					
		>500	E				A	20A				
	Compressed air	<400	A	20A	16A	A	20A	A	Z			
		400-800	E	CER		E		Z	SA			
115	Electric	<900	UC	A	20A	16A	A	20A	A			
		900-1500	UC		E		E		A	Z		
		1500-1750	UC		CER		CER		Z	SA		
	Battery	>300	ACCU				A	20A				
		>500	ACCU				A	20A				
	Compressed air	<600	UC	A	20A	16A	A	20A	A			
		600-900	UC		E		E		A	Z		
		900	UC		CER		CER		Z	SA		
125	Electric	<900	UC	A	20A	16A	A	20A	A			
		900-1500	UC		E		E		A	Z		
		1500-1900	UC		CER		CER		Z	SA		
	Battery	>300	ACCU				A	20A				
		>500	ACCU				A	20A				
	High frequency	<1700	CER				CER		Z	SA		
		Compressed air	<800	UC	A	20A	16A	A	20A	A		
			800-1500	UC		E		E		A	Z	
	1500-2300	UC		CER		CER		Z	SA			
150	Electric	1500-1750	A	20A	16A	E	A	20A	E	A	Z	
		1750-	E		CER		E	CER	Z	SA		
	Compressed air	<2300	CER				CER		Z	SA		
180	Electric	<1800	A	20A	16A	A	20A	A	Z			
		1800-2200	E				E	Z	A	Z		
		2200-	CER				CER	Z	Z	SA		
	High frequency	<3700	E		CER		E	Z	CER	A	Z	SA
		<4500	E		CER		E	Z	CER	A	Z	SA
230	Electric	<2000	A	20A	16A	A	20A	A	Z			
		2500-2600	E				E	Z	Z	SA		
		2600-	CER				CER	Z	Z	SA		
	High frequency	<3700	CER				E	Z	CER	A	Z	
		<4500	CER				E	Z	CER	Z	SA	

## PRODUCT QUALITY MARKS


PROFESSIONAL		EXTRA		SPECIAL	
Quality	Material	Quality	Material	Quality	
A	steel, metal	EA	steel, metal	UC	ultracut
16A	steel + stainless steel	E16A	steel + stainless steel	Z	cirkon
20A	stainless steel	E20A	stainless steel	EZA	cirkon + cer. grain
C	stone			CER	ceramic grain
19A	cast iron			ACCU	cordless
		E54A	aluminum		
		Z	steel + stainless steel		
		SA	ceramic grain		

# LARGE DIAMETERS


Diameter	Machine		Product Quality Mark		
	Drive type	Power (W)	Cutting		
300	Stationary	<4000	A	20A	19A
		4000 - 8000	E		
		>8000	Z		
	Gas	<3500	A	20A	
		>3500	E		
		>3500	Z		
350	Stationary	<4000	A	20A	
		4000 - 8000	E		
		>8000	Z		
	Gas	<4500	A	20A	
		>4500	E		
		>4500	Z		
ChopSaw	<2200	A	20A		
	>2200	E			
	>2200	Z			
400	Stationary	<4000	A	20A	
		4000 - 8000	E		
		>8000	Z		
	Gas	<4500	A		
		>4500	E		
		>4500	Z		

## SELECTING THE BEST GRAIN, GRIT AND GRADE COMBINATION


### Grain



### Grit



### Hardness



## QUALITY MARKING ON PRODUCT




## SAFETY FIRST

### CHOPSAW




### STATIONARY



**DOUBLE**  
FIBERGLASS  
REINFORCEMENT

### GAS SAW



**TRIPLE**  
FIBERGLASS  
REINFORCEMENT